


| Document                            | Version | Date      | Visa    |  |
|-------------------------------------|---------|-----------|---------|--|
| V084_Planken_KannMotionReleaseNotes | 0.8.4   | 28.3.2019 | MSC/MZI |  |

This document describes changes between V0.8.1 to V0.8.4. If you are coming from an older version please refer also to earlier release notes.

## 1 Release Notes KannMotion, StepperConfigTool – 190055 - V0.8.4

| Title        | Group               | Description                    |
|--------------|---------------------|--------------------------------|
| Distribution | <i>New / Change</i> | New firmware 0.8.4 is built in |

## 2 Release Notes KannMotion, PCB-Firmware 190050 .. 190052 - V0.8.4

| Title               | Group         | Description  |
|---------------------|---------------|--|
| AS5600 Encoder Init | <i>BugFix</i> | <ul style="list-style-type: none"> <li>- K24a Controller, Init of Encoder Direction PIN was not done correctly, (Wrong Pin), corrected now at K24a controller firmware</li> <li>- K17ab or K24c controller firmware, no change needed, its just the version index caused by software versioning system!</li> </ul> |

## 3 Detailed Changing Information

## 4 Known unsolved problems

none

## 5 Appendix